



Diary 3.3

## Problems & Solutions:

① 1. The gap of our beam frame will be blocked by motors.

⇒ Install beams in advance

② 2. The distance between 2 motors (at the front) is too close. It's hard to install data line.

⇒ Install lines first.

③ 3. Our machine is designed with great intensity. the fixed parts should be high-firmness

⇒ Change all the nuts to lock nuts

★: Every installation of structure needs to be checked, otherwise after all components

ed by: Migno

witnessed by: Joker

date: 9.29

erty of, and solely owned by the Designer.