

2/12

Driver's Diary - 4

In our practicing competition, because of the similar models, the Robots' speeds are roughly similar. so it is more difficult to defend. In this case, it seemed a better choice to clean up the Triballs in the offensive zone.

In the last 30 seconds, because the front-elevation is now generally more than 1-2 tiers of side-elevation, so the front-elevation Robot need to touch the bar in time after being disturbed, and the side-elevation Robot can disturb the opponent, without greedy 1-2 Triballs.

2/12

Program Improvement

During practice for the skills challenge, we encountered an issue with the rotation sensor. It appeared to have suddenly malfunctioned, possibly due to poor contact.

Unfortunately, we were unable to find a replacement rotation sensor. 



project V5

designed by: Steven

date: 12.2