

3/12 - Diary - 10

In response to the issue we encountered yesterday, we made the following adjustment:

### ① Intake

We replaced the rubber bands on the intake roller, reverting to the previous style with weaker elasticity but stronger toughness. We tightened the rubber bands to improve Triball Intake.

### ② Bumper

After discussing with teammates, we add two short nut columns on the bumper to prevent potential jamming issues.



Figure

project

V5

designed by:

Kevin

witnessed by:

Joker

date:

12.3